

CEN24LA038

INVESTIGATION PHOTOGRAPHS



Photograph 2- Accident Airplane with Cowling Damage in Field (Courtesy of FAA)



Photograph 2 - Accident Airplane with Damaged Vertical Stabilizer (Courtesy of FAA)