

CEN24LA041

INVESTIGATION PHOTOGRAPHS



Photograph 1 -Accident Airplane Alongside Runway 18. (Courtesy of KCFE Airport Ops)



Photograph 2 - Front View of Accident Airplane (Courtesy of KCFE Airport Ops)



Photograph 3 - Top Down View Of Right Wing Lift Struts (Courtesy of FAA)