

CEN24LA050

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Front view at accident site (Courtesy of FAA)**



**Photograph 2 - Airplane at accident site from its front right side (Courtesy of FAA)**



**Photograph 3 - Inboard left wing at accident site (Courtesy of FAA)**