


CEN24LA063

INVESTIGATION PHOTOGRAPHS




Photograph 1 - Accident Overview (Courtesy of Pilot)



Photograph 2 - Fuselage (Courtesy of Pilot)



Photograph 3 - Left Wing Damage (Courtesy of Pilot)



Photograph 4 - Left Magneto & P-Lead Damage (Courtesy of Pilot)