

CEN24LA066

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Substantial Damage to Right Wing (Courtesy of FAA)



Photograph 2 - Substantial Damage to Vertical Stabilizer (Courtesy of FAA)