

CEN24LA077

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Site (FAA Photo)



Photograph 2 - Accident Site (FAA Photo)



Photograph 3 - Engine (NTSB Photo)



Photograph 4 - Engine (NTSB Photo)



Photograph 5 Fuel Pump (NTSB Photo)



Photograph 6 - Fuel Pump Debris (NTSB Photo)