

CEN24LA087

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the airplane and airport right before the accident (Courtesy of the pilot)




Photograph 2 - View of the right side of the airplane (Courtesy of the pilot)



Photograph 3 - View of the front of the airplane (Courtesy of the pilot)



Photograph 4 - View of the left side of the airplane (Courtesy of the pilot)



Photograph 5 - View of the tall trees that the airplane impacted near the runway (Courtesy of the pilot)