

National Transportation Safety Board

Office of Aviation Safety
Central Region

CEN24LA100

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident airplane damage (Courtesy of FAA).



Photograph 2 - Damage to front of airplane (Courtesy of FAA).



Photograph 3 - Left wing damage (Courtesy of FAA).