

☐ HUB & BLADE

Year: JAN 4 To in

Date: 2022

Next Inspection Due: To On

Year: SEP To in

Date: 15 23

Next Inspection Due: To On

Year: To in

Date:

Next Inspection Due: Time Overhaul

JORDAN PROPELLER SERVICE, INC.

San Antonio, Texas 78216

Certificated Repair Station No. EK2R797K

PROPELLER S/N E13077 HAS BEEN REPAIRED

REFERENCE McCauley Manual 730720.

Performed Minor Blade Straightening To Tip Of Blade No. 2 To Repair Freight Shipping Damage.

PERTINENT DETAILS ON FILE UNDER WORK ORDER 21553

SIGNED [REDACTED] DATE 02/Oct/2020

MECHANIC MAKING INSTALLATION ON A/C MUST C/W FAR 43.9

Mech. Ce [REDACTED] Repair Station # [REDACTED]

☐ HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Year: <u>JAN 4</u>	Total Time in Service	Description <u>installed new propeller E-13077</u> <u>TACH 2971.1</u>
Date: <u>2022</u>	<u>0</u>	
Next Inspection Due:	Time Since Overhaul	Mech. Cert. # or Repair Station # <u>[REDACTED] AIP [REDACTED]</u>
	<u>0</u>	

Year: <u>SEP</u>	Total Time in Service	Description <u>INSPECTED IAW A 100 hour</u> <u>inspection & determine to be in</u> <u>AIRworthy condition</u>
Date: <u>11 23</u>	<u>3276</u>	
Next Inspection Due:	Time Since Overhaul	Mech. Cert. # or Repair Station # <u>[REDACTED] AIP [REDACTED]</u>

Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due:	Time Since Overhaul	

EASA Form 1 - ME1145 Issue 2 / 10082-03

13d. Name
Nome

13b. Authorised Signature
Assinatura autorizada

13a. Certifies that the items identified
Certifica-se que os elementos supramencionados
☐ approved design data and
dados de projecto aprovados e qu
☐ non-approved design data
dados de projecto não aprovados e

12. Remarks / Observações

Propeller OVERHAULED IAW MCCAULEY
No. SPM 100 - Rev. 6 Dtd. OCT 2011
Propeller TSN: UNK. and TSO: 00:00

6. Item Artigo	7. Description Descrição
01	PROPELLER MCCAULEY

1. Approving Competent Authority
Entidade de certificação competente /
ANAC / PORTUGAL
4. Organization Name and Address
Nome e endereço da entidade