

CEN24LA102

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the front of the airplane at the accident site (courtesy of the Federal Aviation Administration)



Photograph 2 - View of the left side of the airplane at the accident site (courtesy of the Federal Aviation Administration)



Photograph 3 - View of the rear of the airplane at the accident site (courtesy of the Federal Aviation Administration)



Photograph 4 - View of the right side of the airplane at the accident site (courtesy of the Federal Aviation Administration)



Photograph 5 - View of the fuselage and the engine during the examination



Photograph 6 - View of the wings during the examination



Photograph 7 - View of the engine during the examination



Photograph 8 - View of the propeller during the examination



Photograph 9 - View of the fuel measuring stick found inside of the cockpit during the examination