

NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: 405 - Cherokee Munciple Airport State: OK

ZIP: 73728 Country: United States

Latitude: 36.78236° N Longitude: 98.35834° W

(Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/Time

Date: 02/02/2024 Local Time: 10:42L
mm/dd/yyyy

Time Zone: Central

Collision with Other Aircraft: ☐ Midair ☐ On-ground ☒ None

AIRCRAFT INFORMATION

Registration Number: N4284

Manufacturer: Piper

Model: PA-24-260

Serial Number: 24-4284

Year of Manufacture: 1965

Amateur-Built: ☐ Yes ☒ No If Yes: ☐ Kit/Plans ☐ Original Design Make: _____

☒ IFR-Equipped and Certified

☐ Commercial Space Flight

☐ Unmanned Aircraft

Maximum Gross Weight: 2900 lbs

Weight at Time of Accident/Incident: 2550 lbs

Number of Seats: 4 Flight Crew Seats: _____

Cabin Crew Seats: _____ Passenger Seats: _____

Number of Engines: 1

Category of Aircraft

- ☒ Airplane
- ☐ Balloon
- ☐ Blimp/Dirigible
- ☐ Glider
- ☐ Gyroplane
- ☐ Helicopter
- ☐ Powered Lift
- ☐ Rocket
- ☐ Ultralight
- ☐ Unknown

Type of Airworthiness Certificate

(Check all that apply)

Standard

- ☒ Normal
- ☐ Aerobatic
- ☐ Balloon
- ☐ Commuter
- ☐ Transport
- ☐ Utility

Special

- ☐ Restricted
- ☐ Limited
- ☐ Provisional
- ☐ Special Flight
- ☐ Experimental
- ☐ Special Light-Sport
- ☐ Experimental Light-Sport

- ☐ Certificate of Authorization or Waiver (COA)
- ☐ None
- ☐ Unknown

Landing Gear

(Check all that apply)

☒ Retractable

- ☐ Tricycle
- ☐ Amphibian
- ☐ Emergency Float
- ☐ Float
- ☐ Hull
- ☐ Other Launch/Recovery System
- ☐ None
- ☐ Tailwheel
- ☐ High Skid
- ☐ Skid
- ☐ Ski
- ☐ Ski/Wheel
- ☐ Unknown

Engine Type (Select one)

- ☒ Reciprocating
- ☐ Turbo Shaft
- ☐ Turbo Prop
- ☐ Turbo Jet
- ☐ Turbo Fan
- ☐ Electric
- ☐ Liquid Rocket
- ☐ Solid Rocket
- ☐ Hybrid Rocket
- ☐ None
- ☐ Unknown

Fuel System Type (Reciprocating)

- ☐ Carburetor
- ☒ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Series	Manufacturer's Serial Number	Date of Mfg. mm/dd/yyyy	Rated Power ☒ Horsepower or ☐ lbs of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng. 1	<u>Lycoming</u>	<u>IO-540-D4A5</u>	<u>L-1727-48</u>		<u>260</u>		<u>48.3</u>	<u>2009.5</u>
Eng. 2								
Eng. 3								
Eng. 4								

Last Inspection Type

- ☐ 100-Hour
- ☐ AAIP
- ☒ Annual
- ☐ Continuous Airworthiness
- ☐ Conditional Inspection
- ☐ Unknown

Date Last Inspection: 11/07/2023
mm/dd/yyyy

Airframe Total Time: 6770.4 hrs

hours measured at (Select one)

- ☐ Last Inspection
- ☒ Time of Accident/Incident

Type of Maintenance Program (Select one)

- ☒ Annual
- ☐ Conditional (Amateur-built only)
- ☐ Manufacturer's Inspection Program
- ☐ Other Approved Inspection Program (AAIP)
- ☐ Continuous Airworthiness
- ☐ Other, specify: _____

Description of Fire Extinguishing System

- ☒ None
- ☐ Specify: _____

Propeller 1

- ☐ Fixed Pitch
- ☒ Controllable Pitch
- ☐ Ground Adjustable

Manufacturer: Hartzell

Model: HC-C3YR-1RF/F7590

Propeller 2

- ☐ Fixed Pitch
- ☐ Controllable Pitch
- ☐ Ground Adjustable

Manufacturer: _____

Model: _____

ELT Installed: ☒ Yes ☐ No

If Yes:

ELT Manufacturer: ARTEX

Model or Part No.: ME406

TSO No.: ☐ OC91 (121.5 MHz) ☐ OC91a (121.5 MHz)
☒ C126 (406 MHz)

Was ELT still mounted in aircraft? ☒ Yes ☐ No

Was ELT still connected to antenna? ☒ Yes ☐ No

Did ELT Activate? ☒ Yes ☐ No

If activated:

Did ELT Aid in Locating Aircraft? ☒ Yes ☐ No

If not activated:

- Indicate Reason:
- ☐ Impact Damage
 - ☐ Fire Damage
 - ☐ Battery Expired/Damaged
 - ☐ Unknown

Additional Equipment (Check all that apply)

- ☒ ADS-B
- ☐ Airframe Parachute
- ☐ Angle of Attack Indicator
- ☐ Autopilot
- ☐ Data Recorder
- ☐ Electronic Flight Bag or Handheld Device
- ☒ Electronic Multifunction Display
- ☒ Electronic Primary Flight Display
- ☐ Handheld GPS
- ☐ Heads Up Display
- ☒ Onboard Weather
- ☐ Satellite Tracking Device
- ☒ Stall Warning System
- ☐ Video Recording Device
- ☐ Other, Specify: _____

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**Name: Eric ClementsCity: SheridanFractional Ownership Aircraft: ☐ Yes ☒ NoState: WY ZIP: 82801Country: United States**Operator of Aircraft**☒ Same As Registered Owner☒ Same Address as Registered Owner

Name: _____

City: _____

Doing Business As: _____

State: _____ ZIP: _____

Air Carrier/Operator Designator (4 Character Code): _____

Country: _____

Operating Certificates Held

(Check all that apply)

- ☐ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☐ Rotorcraft External Load (FAR 133)
☐ Commuter Air Carrier (FAR 135)
☐ On-Demand Air Taxi (FAR 135)
☐ Commercial Air Tour (FAR 136)
☐ Agricultural Aircraft (FAR 137)
☐ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☒ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☐ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437
- ☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial
- ☐ Public Aircraft (Select one)
☐ Armed Forces
☐ Federal
☐ State
☐ Local
☐ Unknown

Revenue Operation for FAR 121, 125, 129, 135

(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International
- ☐ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137

(Select one)

- ☐ Aerial Application ☐ Firefighting ☐ Unknown
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☐ Air Race/Show ☐ Instructional
☐ Banner Tow ☐ Other Work Use
☐ Business ☒ Personal
☐ Executive/Corporate ☐ Positioning
☐ External Load ☐ Skydiving
☐ Ferry

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)**Airport Name: Cherokee Municipal AirportDistance From Airport Center: 0.4 smAirport Identifier: 405Direction From Airport: 180 degrees trueProximity to Airport: ☒ Off Airport/Airstrip ☐ On Airport/Airstrip ☐ N/AAirport Elevation: 1179 ft. msl**Runway Information**Runway ID: 17 (L/R/C) Length: 3770 ft Width: 60 ft**Runway/Landing Surface (Check all that apply)**

- ☒ Asphalt ☐ Grass/Turf ☐ Macadam ☐ Water
☐ Concrete ☐ Gravel ☐ Metal/Wood
☐ Dirt ☐ Ice ☐ Snow ☐ Unknown

Condition of Runway/Landing Surface (Check all that apply)

- ☒ Dry ☐ Snow-Compacted ☐ Water-Calm
☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☐ Wet
☐ Rubber Deposits ☐ Soft
☐ Slush-Covered ☐ Vegetation ☐ Unknown

Approach/Departure Segment (Select one)

- ☐ Taxi ☐ VFR Departure ☐ On Instrument Approach ☐ Downwind ☐ Low Approach
☐ Takeoff ☐ IFR Departure Procedure/Clearance ☐ Landing ☐ Base ☐ Go Around
☐ Initial Climb ☐ Aborted Landing (after touchdown)
☐ Crosswind ☐ Unknown

IFR Approach (Check all that apply)

- ☒ None
- ☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
☐ VOR/TVOR ☐ ILS ☐ ASR
☐ VOR/DME ☐ Localizer Only ☐ Visual
☐ TACAN ☐ LOC-back course ☐ Contact
☐ RNAV ☐ Circling
☐ Unknown

VFR Approach (Check all that apply)

- ☐ None
- ☐ Traffic Pattern ☐ Stop and Go
☐ Straight-In ☐ Touch and Go
☐ Valley/Terrain Following ☐ Simulated Forced Landing
☐ Go Around ☒ Forced Landing
☐ Full Stop ☐ Precautionary Landing
☐ Unknown

"FLIGHT CREWMEMBER 1" INFORMATION**"Flight Crewmember 1" Responsibilities at the Time of Accident/Incident**

☒ Pilot ☐ Co-Pilot ☐ Student Pilot ☐ Flight Instructor ☐ Check Pilot ☐ Flight Engineer ☐ Other Flight Crew

"Flight Crewmember 1" was pilot flying ☒ Yes ☐ No

"Flight Crewmember 1" Identification

First Name: Eric

City of Residence: Enid

Middle Initial: C

State: OK ZIP: 73701

Last Name: Clements

Country: United States

Age at time of Accident/Incident: 41 Date of Birth: [REDACTED] mm/dd/yyyy

Certificate Number: [REDACTED]

Degree of Injury

☒ None ☐ Fatal
☐ Minor ☐ Unknown
☐ Serious

Seat Occupied

☒ Left ☐ Front ☐ Unknown
☐ Right ☐ Rear
☐ Center ☐ Single

Restraint Type**Available**

☐ None
☐ Lap only
☒ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Used

☐ None
☐ Lap only
☒ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Inflatable Restraints

☒ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None ☒ Flight Instructor ☒ Commercial ☒ US Military
☒ Private ☐ Recreational ☐ Airline Transport ☐ Foreign
☐ Student ☐ Sport ☐ Flight Engineer

Principal Occupation

☒ Pilot
☐ Other
☐ Unknown

Medical Certificate

☐ None ☒ Class 3
☐ Class 1 ☐ Driver's License (Sport Pilot only)
☐ Class 2 ☐ Unknown

Medical Certificate Validity

☐ Without limitations/waivers ☐ Unknown
☒ With limitations/waivers ☐ N/A
☐ Special Issuance

Date of Last Medical

07/26/1982
mm/dd/yyyy

Medical Certificate Limitations

Required to wear glasses and carry a spare pair.

Medical Certificate Special Issuance

Military DD-Form 2992

**Date of Last Flight Review
or Equivalent, Including
FAR 121/135 Checks:**

12/06/2022
mm/dd/yyyy

Flight Review Aircraft

Make: Military, Beechcraft

Model: T-6A

Airplane Rating(s)
(Check all that apply)

☐ None
☒ Single-Engine Land
☐ Single-Engine Sea
☒ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s)
(Check all that apply)

☐ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s)
(Check all that apply)

☐ None
☒ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s)
(Check all that apply)

☐ None ☒ Instrument Airplane
☒ Airplane Single-Engine ☐ Instrument Helicopter
☒ Airplane Multi-Engine ☐ Helicopter
☐ Gyroplane ☐ Glider
☐ Powered Lift ☐ Sport

Type Ratings

MU-300, BE-400, B-707, B-720

Student Endorsements (Include dates)

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	6610.8	113.1	4402.8	2208.0	680.0	307.0	7.7			
Pilot in Command (PIC)	5079.4	112.6	4079.8	1001.1						
Time as Instructor	4075.0	0	3661.3	411.1						
This Make/Model										
Last 90 Days	122.5	47.4	122.5	0						
Last 30 Days	30.3	5.4	30.3	0						
Last 24 Hours	2.4	2.4	2.4	0						

“FLIGHT CREWMEMBER 2” INFORMATION

“Flight Crewmember 2” Responsibilities at the Time of Accident/Incident

☐ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

“Flight Crewmember 2” was pilot flying ☐ Yes ☐ No

“Flight Crewmember 2” Identification

First Name: _____ City of Residence: _____
 Middle Initial: _____ State: _____ ZIP: _____
 Last Name: _____ Country: _____
 Age at time of Accident/Incident: _____ Date of Birth: _____ mm/dd/yyyy
 Certificate Number: _____

Degree of Injury

☐ None ☐ Fatal
☐ Minor ☐ Unknown
☐ Serious

Seat Occupied

☐ Left ☐ Front ☐ Unknown
☐ Right ☐ Rear
☐ Center ☐ Single

Restraint Type

Available

☐ None
☐ Lap only
☐ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Used

☐ None
☐ Lap only
☐ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Inflatable Restraints

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military
☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign
☐ Student ☐ Sport ☐ Flight Engineer

Principal Occupation

☐ Pilot
☐ Other
☐ Unknown

Medical Certificate

☐ None ☐ Class 3
☐ Class 1 ☐ Driver's License (Sport Pilot only)
☐ Class 2 ☐ Unknown

Medical Certificate Validity

☐ Without limitations/waivers ☐ Unknown
☐ With limitations/waivers ☐ N/A
☐ Special Issuance

Date of Last Medical

_____ mm/dd/yyyy

Medical Certificate Limitations

Medical Certificate Special Issuance

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

_____ mm/dd/yyyy

Flight Review Aircraft

Make: _____

Model: _____

Airplane Rating(s) (Check all that apply)

☐ None
☐ Single-Engine Land
☐ Single-Engine Sea
☐ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s) (Check all that apply)

☐ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s) (Check all that apply)

☐ None
☐ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s) (Check all that apply)

☐ None ☐ Instrument Airplane
☐ Airplane Single-Engine ☐ Instrument Helicopter
☐ Airplane Multi-Engine ☐ Helicopter
☐ Gyroplane ☐ Glider
☐ Powered Lift ☐ Sport

Type Ratings

Student Endorsements (Include dates)

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time										
Pilot in Command (PIC)										
Time as Instructor										
This Make/Model										
Last 90 Days										
Last 30 Days										
Last 24 Hours										

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information)									
Crew Name and Address					Seat Occupied		Injury		
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign					Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs						
Crew Name and Address					Seat Occupied		Injury		
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign					Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs						
PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet if necessary)									
Name and Address			Seat	Injury	Restraint Type		Inflatable Restraints	Age	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	

FLIGHT ITINERARY INFORMATION

Last Departure Point Airport ID: <u>KWDG</u> City: <u>Enid</u> State: <u>OK</u> Country: <u>United States</u>	Time of Departure Time: <u>09:55L</u> Time Zone: <u>Central</u>	Destination Airport ID: <u>KWDG (Planned)</u> City: <u>Enid</u> State: <u>OK</u> Country: <u>United States</u>	Type Flight Plan Filed ☒ None ☐ VFR/IFR ☐ Company VFR ☐ IFR ☐ Military VFR ☐ Unknown ☐ VFR Activated? ☐ Yes ☒ No ☐ Unknown
--	--	---	--

Type of ATC Clearance/Service (Check all that apply) ☐ None ☐ Special VFR ☐ Special IFR ☐ VFR Flight Following ☐ Cruise ☒ VFR ☐ IFR ☐ VFR On Top ☐ Traffic Advisory ☐ Unknown / NA			
Airspace where the accident/incident occurred (Check all that apply) ☐ Class A ☒ Class G ☐ Military Operations Area (MOA) ☐ Special ☐ Class B ☐ Demo Area ☐ Airport Advisory Area ☐ Air Traffic Control Area ☐ Class C ☐ Warning Area ☐ Jet Training Area ☐ Unknown ☐ Class D ☐ Prohibited Area ☐ TRSA ☐ Class E ☐ Restricted Area ☐ FAR 93			Altitude of In-Flight Occurrence: <u>1179</u> ft msl

WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE

Source of Pilot Weather Information (Check all that apply) ☒ National Weather Service ☐ Company ☐ Flight Service Station ☐ Military ☐ TV/Radio ☒ Internet ☐ Automated Report ☐ None ☐ Commercial Weather Service (DUATS) ☐ Unknown ☒ On-Board Weather		Weather Observation Facility Facility ID: <u>KWDG</u> Observation Time: <u>0950L</u> Time Zone: <u>Central</u> Distance from Accident Site: <u>37</u> nm Direction from Accident Site: <u>310</u> degrees true																													
Basic Conditions ☒ VMC ☐ IMC ☐ Unknown		Light Condition ☐ Dawn ☐ Dusk ☐ Dark Night ☐ Unknown ☒ Day ☐ Night ☐ Bright Night																													
Sky/Lowest Cloud Condition ☐ Clear ☐ Thin Broken ☐ Few ☐ Thin Overcast ☐ Partial Obscuration ☒ Unknown ☐ Scattered Lowest Cloud Condition Height <u>Ground Fog sfc-200</u> ft agl		Ceiling ☐ None (Clear) ☒ Obscured ☐ Broken ☐ Indefinite ☐ Overcast ☐ Unknown Ceiling Height <u>clear above 200</u> ft agl																													
Wind Direction ☐ Variable -or- Direction: <u>140</u> degrees true		Wind Speed ☐ Calm ☐ Light and Variable -or- Speed: <u>10</u> kts	Wind Gusts ☒ Not Gusting -or- Speed: _____ kts																												
Intensity of Precipitation ☐ Light ☐ Moderate ☐ Heavy ☒ N/A ☐ Unknown		Type of Precipitation (Check all that apply) ☒ None ☐ Drizzle ☐ Freezing Rain ☐ Rain ☐ Ice Pellets ☐ Snow Shower ☐ Snow ☐ Snow Pellets ☐ Ice Pellets Shower ☐ Hail ☐ Snow Grains ☐ Freezing Drizzle ☐ Rain Showers ☐ Ice Crystals																													
Restriction to Visibility (Check all that apply) ☐ None ☐ Fog ☐ Blowing Dust ☒ Ground Fog ☐ Blowing Sand ☐ Haze ☐ Blowing Snow ☐ Ice Fog ☐ Blowing Spray ☐ Smoke ☐ Dust ☐ Unknown		Visibility <u>0.1 (at sfc)</u> miles RVR: _____ feet RVV: _____ miles Density Altitude: <u>1500</u> ft																													
Icing Forecast <table border="0"> <tr> <th>Amount</th> <th>Type</th> </tr> <tr> <td>☒ None</td> <td>☐ N/A</td> </tr> <tr> <td>☐ Trace</td> <td>☐ Rime</td> </tr> <tr> <td>☐ Light</td> <td>☐ Clear</td> </tr> <tr> <td>☐ Moderate</td> <td>☐ Mixed</td> </tr> <tr> <td>☐ Severe</td> <td>☐ Unknown</td> </tr> <tr> <td>☐ Unknown</td> <td></td> </tr> </table>		Amount	Type	☒ None	☐ N/A	☐ Trace	☐ Rime	☐ Light	☐ Clear	☐ Moderate	☐ Mixed	☐ Severe	☐ Unknown	☐ Unknown		Icing Actual <table border="0"> <tr> <th>Amount</th> <th>Type</th> </tr> <tr> <td>☒ None</td> <td>☐ N/A</td> </tr> <tr> <td>☐ Trace</td> <td>☐ Rime</td> </tr> <tr> <td>☐ Light</td> <td>☐ Clear</td> </tr> <tr> <td>☐ Moderate</td> <td>☐ Mixed</td> </tr> <tr> <td>☐ Severe</td> <td>☐ Unknown</td> </tr> <tr> <td>☐ Unknown</td> <td></td> </tr> </table>		Amount	Type	☒ None	☐ N/A	☐ Trace	☐ Rime	☐ Light	☐ Clear	☐ Moderate	☐ Mixed	☐ Severe	☐ Unknown	☐ Unknown	
Amount	Type																														
☒ None	☐ N/A																														
☐ Trace	☐ Rime																														
☐ Light	☐ Clear																														
☐ Moderate	☐ Mixed																														
☐ Severe	☐ Unknown																														
☐ Unknown																															
Amount	Type																														
☒ None	☐ N/A																														
☐ Trace	☐ Rime																														
☐ Light	☐ Clear																														
☐ Moderate	☐ Mixed																														
☐ Severe	☐ Unknown																														
☐ Unknown																															
Turbulence Type (Check all that apply) ☒ None ☐ Clear Air ☐ Terrain-Induced ☐ Convective Turbulence Severity ☐ Light ☐ Moderate ☐ Severe ☐ Extreme																															

NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident:

N/A

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- ☐ None ☐ Substantial
☐ Minor ☒ Destroyed
 ☐ Unknown

Aircraft Fire

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Fire at Unknown Time
☐ On-Ground ☐ Unknown

Aircraft Explosion

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Explosion at Unknown Time
☐ On-Ground ☐ Unknown

Description of Damage to Aircraft and Other Property *(Use additional sheet if necessary)*

Aircraft flew through airport chainlink fence/gate (damaged).

Aircraft flew through land-owner barbed-wire fence and damaged field.

Aircraft right wing destroyed, left wing substantial damage. Airframe and fuselage bent and twisted. Landing gear destroyed. Left main gear and nose gear ripped off. Belly of aircraft significantly damaged/destroyed. Stabilator substantially damaged. Nose/cowling substantially damaged. Engine major damage. Propeller destroyed.

Loss of engine power while airborne (2500 feet MSL) caused the attempted emergency landings at 4O5; Engine was not operating correctly prior to and during crash.

NARRATIVE HISTORY OF FLIGHT *(Please type or print in ink)*

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

I departed from KWDG at approximately 0955L (1555Z) from runway 17 (winds were 140/10 knots, altimeter 29.77, sky clear, unlimited visibility). I climbed to 6,500 feet MSL while meandering northwest underneath the Vance 1B MOA's. I flew VFR, and maintained VMC the entire route of flight until the crash.

At approximately 1020L (1620Z) I began a descent in a southern direction with the intent to fly at approximately 2,500 feet MSL. While down low, at approximately 1037L (1637Z) the engine began running very rough and sounded bad. I advanced the mixture, propeller, and throttle full forward in an attempt to increase RPM and I attempted to climb while turning toward the nearest airfield (4O5).

While enroute to 4O5 I checked both magneto's (individually) hoping the problem was a bad magneto. The engine problems did not disappear during either magneto check. I also checked the fuel gauges and fuel selector position, with no indications of problems.

The airfield was covered in ground fog and I could not see the runway very well from above, but I decided to attempt a landing. Due to the poor visibility I made a poor (long) approach to the runway. I lowered the landing gear and touched down approximately (or more than...I'm not sure) half way down the runway. As the wheels were touching down I attempted to go-around, but with the gear down I had insufficient power to climb. The aircraft struck the airport fence, flew across the road and through a private land-owner's fence, and skidded to a halt approximately 500 south of the runway threshold. During the collision with the fences the nose-gear and right main gear were ripped off the aircraft and during the skid the aircraft rotated (yawed) clockwise from a heading of 175 to a heading of approximately 030. The aircraft was on the ground and stopped at approximately 1042L (1642Z). After the aircraft was stopped I turned off all electrical switches. I turned off the ELT (which had been activated) and I climbed out of the aircraft.

When firefighters responded to the crash they directed me to turn the fuel selector switch to off and to disconnect the battery. I assisted them in doing these two things. At the time of the crash the aircraft had approximately 70 gallons of fuel and that fuel was leaking into the field.

1044L (1644Z): I called 911 and notified them of the accident.

1112L (1712Z): I contacted NTSB.

1130L (1730Z): I contacted my insurance company.

1145L (1745Z): I was in contact with FAA.

Tail Number: N4284

Piper Comanche 260

PA-24-260

Engine was a Lycoming IO-540-D4A5

Tach time is approximately 6770.4

Time since last overhaul: 2009.55

Last Annual: Completed: 7 November 2023 (Webco Aircraft, Newton, KS)

Last Oil Change: 29 Jan 2024.

All AD's complied with.

No previous problems prior to this flight.

RECOMMENDATION (How could this accident/incident have been prevented?)

Operator/Owner Safety Recommendation

In this particular case, if the airport would have had an RNAV approach to either 17 or 35 I could have used course guidance more effectively to attempt a landing through the ground fog.

In this case, my engine had lost significant power and I could not maintain airspeed and altitude...I was in a bad situation due to the low-level ground fog. I think if the fog hadn't been there I would have landed safely. The Alva Airport (KAVK) was 15NM away...it is possible that I might have been able to try an RNAV approach there...but I don't think I could make it since I was losing both altitude and airspeed.

- In hind site...I should have flown slightly further north of 405 and then attempted to get on a 175 OBS course to the airport center further to the North. (I was also worried about hitting the power lines on the west side of the airport...they were in the fog)

I do not have any useful safety recommendations to prevent mishaps like this in the future.

-Had I been flying at a higher altitude I would have had more range/time to work the problem.

-Had I been in an area with less ground fog I could have picked out a field to land in.

-Had I put my gear down sooner I might have touched down sooner....or I might have crashed short of the airport.

-I don't know, this one was tough...I guess, don't be over ground-fog when your engine fails.

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)

Was there Mechanical Malfunction/Failure? ☒ Yes ☐ No

(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

Lycoming IO-540-D4A5, Serial Number: L-1727-48, 2009.5 SMOH. At 2500 feet MSL, 2200RPM, and approx 16 gph fuel flow (rich of peak) (unknown manifold pressure...probably around 24-26). The engine suddenly started running very rough and making bad noises. Airspeed immediately dropped off. Changing RPM, throttle, and mixture did not change the behavior of the engine. After confirming fuel flow and quantity, I checked both magnetos (individually) (hoping one mag had gone bad), however turning off either magneto individually did not reduce or solve the problem. At max throttle, and RPM I could not maintain airspeed or climb. During the attempted emergency landing I attempted to go-around to get over the fence with the gear down and had insufficient power to climb or accelerate. I do not know what was wrong with the engine.

**Total Time/Cycles
On Part**

_____ Hours

_____ Cycles

**Time Since This Part
Inspected/Overhauled**

2009.5 _____ Hours

FUEL & SERVICES INFORMATION**Fuel on Board at Last Takeoff**

(Convert from pounds, as necessary)

90 (86 usable) _____ Gallons

Fuel Type

☐ 80/87

☐ 115/145

☐ Jet B

☐ Other, specify _____

☒ 100 Low Lead

☐ Jet A

☐ JP8

☐ 100/130

☐ Jet A-1

☐ Automotive

Other Services, if Any, Prior to Departure**EVACUATION OF AIRCRAFT**

Was an emergency evacuation of the aircraft performed? ☒ Yes ☐ No

Method of Exit – Describe how the occupants exited and how many occupants evacuated each location

I unbuckled my seat-belt (with shoulder harness) and opened the cabin door...then climbed out.

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for other aircraft)

Aircraft Registration Number

Manufacturer: _____

Model: _____

Damage to Other Aircraft

☐ Destroyed

☐ Minor

☐ Substantial

☐ None

Registered Owner of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

Pilot of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

The engine seemed to be running fine...with no issues at all up to this point. The aircraft had made several long sorties over the last two months.

The start and engine-run-up was normal with about 50 RPM drop on each magneto at 2200RPM.

The number 5 cylinder was running the hottest...sometimes reaching 400 degrees, but was manageable by changing the mixture or throttle. The majority of the sortie I attempted to keep the CHT for #5 at or below 380...but it varied.

The other cylinders seemed okay, with cylinders 4 and 6 having lower EGT's and CHT's....but all within normal ranges.

I do not know what the engine problem was.

After reviewing ADS-B data, I do not think I could have limped the aircraft to KAVK, and I'm not sure the ground fog would have been any better. The ground fog did not exist over some the "Salt Plains" (Great Salt Lake just East of 405). There were also areas with no-ground fog north of my engine problem position (that I had just overflowed a few minutes earlier), it is possible I could have found a better road or a field to land it if I had turned towards those areas...though I don't know.

After the aircraft was stopped on the ground and I was in contact with fire-fighters I assisted fire-fighters in disconnecting the aircraft battery and moving the fuel selector to the off position.

A large amount of fuel leaked out of the wings into the field. At the time of the mishap, the aircraft had approximately 70 gallons of fuel onboard.

When FAA inspectors arrived at the scene, the oil level was checked; the oil quantity was 9 quarts which matched the approximate oil quantity prior to takeoff. Additionally, inspectors opened the engine cowling but no obvious cause/damage to the cylinders was visible at that time.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE

Date of this Report

02/05/2024
mm/dd/yyyy

Name of Pilot/Operator:

ERIC CLEMENTS

Signature:

-- or --



Check here to electronically sign this document

If a Person Other than Pilot/Operator is Filing Report

Name: _____

Title: _____

Signature: _____

-- or --



Check here to electronically sign this document

FOR NTSB USE ONLY

NTSB Accident/Incident No.

CEN24LA104

Reviewed by NTSB Regional Office

Central Region

Name of Investigator

T. Sorensen

Date Report Received

February 5, 2024