

CEN24LA107

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Airplane - Left Wing (Courtesy of FAA)



Photograph 2 - Accident Airplane - Forward Fuselage and Engine/Cowling (Courtesy of FAA)



Photograph 3 - Accident Airplane - Front View (Courtesy of FAA)



Photograph 4 - Accident Airplane - Empennage - (Courtesy of FAA)