

National Transportation Safety Board

Office of Aviation Safety
Central Region

CEN24LA109

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident airplane prior to recovery (Provided by law enforcement)



Photograph 2 - Wing damage - photo taken after recovery of airplane (Courtesy of a friend of pilot)



Photograph 3 - Accident airplane after recovery from river (Courtesy of a friend of the pilot)



Photograph 4 - Accident airplane after recovery (Courtesy of a friend of the pilot)