

CEN24LA110

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Pipistrel Glider with Damaged Left Wing (Courtesy of FAA)



Photograph 2 - Pipistrel Glider with Damaged Left Wing (Courtesy of FAA)