

National Transportation Safety Board

Office of Aviation Safety
Central Region

CEN24LA113

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident airplane (Courtesy of FAA)



Photograph 2 - Damaged left wing and vertical stabilizer (Courtesy of FAA)



Photograph 3 - Damaged left wing and wing struts (Courtesy of FAA)