

National Transportation Safety Board

Office of Aviation Safety
Central Region



CEN24LA114

INVESTIGATION PHOTOGRAPHS



**Photo 1 - Airplane at accident site, left
(Courtesy of FAA)**



**Photo 2 - Airplane at accident site, front
(Courtesy of FAA)**



**Photo 3 - Left wing damage
(Courtesy of FAA)**



**Photo 4 - Fuel gauges
(Courtesy of FAA)**