

CEN24LA123

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the left side of the airplane (courtesy of the Federal Aviation Administration)



Photograph 2 - View of the front of the airplane (courtesy of the Federal Aviation Administration)



Photograph 3 - View of the right side of the airplane (courtesy of the Federal Aviation Administration)