

National Transportation Safety Board

Office of Aviation Safety
Central Region

CEN24LA126

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident airplane (Courtesy of airport manager)



Photograph 2 - Accident airplane (Courtesy of airport manager)



**Photograph 3 - Accident airplane right wingtip
(Courtesy of airport manager)**



**Photograph 4 - Accident airplane right wheel and tire assembly
(Courtesy of airport manager)**