

CEN24LA128

T-BOLT PHOTOGRAPHS



Photograph 1 - Rear fuselage hole (Courtesy of Metro Aviation)



Photograph 2 - Rear fuselage hole (Courtesy of Metro Aviation)



Photograph 3 - T-Bolt as found (Courtesy of Metro Aviation)



Photograph 4 - T-Bolt as found (Courtesy of Metro Aviation)



Photograph 5 - T-Bolt hole (Courtesy of Metro Aviation)



Photograph 6 - T-Bolt as found (Courtesy of Metro Aviation)



Photograph 7 - T-Bolt as found (Courtesy of Metro Aviation)