

CEN24LA129

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Helicopter Canopy Damage (Courtesy of Federal Aviation Administration)



Photograph 2 - Yellow Rotor Blade Damage (Courtesy of Federal Aviation Administration)



Photograph 3 - Pilot's Helmet Damage (Courtesy of Federal Aviation Administration)