

CEN24LA140

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front view of airplane (Courtesy of FAA)



Photograph 2 - Right wing view of airplane (Courtesy of FAA)



Photograph 3 - Cowling damage (Courtesy of FAA)



Photograph 4 - Engine and cowling view (Courtesy of FAA)



Photograph 6 - Damage to Engine (Courtesy of FAA)