

CEN24LA144

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the front of the partial fuselage at the accident site (courtesy of the Federal Aviation Administration)



Photograph 2 - View of the left side of the partial fuselage at the accident site (courtesy of the Federal Aviation Administration)



Photograph 3 - View of the rear of the partial fuselage at the accident site (courtesy of the Federal Aviation Administration)



Photograph 4 - View of the right side of the partial fuselage at the accident site (courtesy of the Federal Aviation Administration)



Photograph 5 - View of the partial fuselage and the engine during the examination



Photograph 6 - View of multiple airframe sections during the examination



Photograph 7 - View of the engine during the examination



Photograph 8 - View of the cockpit during the examination



Photograph 9 - View of the propeller during the examination



Photograph 10 - View of the propeller blades during the examination