

CEN24LA149

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the front of the airplane on the runway (courtesy of the Federal Aviation Administration).



Photograph 2 - View of the left side of the airplane on the runway (courtesy of the Federal Aviation Administration).




Photograph 3 - View of the right side of the airplane on the runway (courtesy of the Federal Aviation Administration).



Photograph 4 - View of the nose landing gear on the runway (courtesy of the Federal Aviation Administration).



Photograph 5 - View of the substantial damage sustained to the left side cockpit floor (courtesy of the Federal Aviation Administration).



**Photograph 6 - View of the substantial damage sustained to the right side cockpit floor
(courtesy of the Federal Aviation Administration).**