

[CEN24LA159]


INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Airplane (Courtesy of FAA)



Photograph 2 - Substantial Engine Mount Damage (Courtesy of FAA)



Photograph 3 - Substantial Engine Firewall Damage (Courtesy of FAA)