

CEN24LA165

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right side (Courtesy of law enforcement)



Photograph 2 - Left rear (Courtesy of law enforcement)



Photograph 3 - Left wing damage (Courtesy of law enforcement)