

Date: April 29, 2024

Subject: CEN24LA168 - Security Cameras

Two security cameras captured the final portion of the accident flight.

The first camera angle shows a single-story metal building. The camera timestamp is 00:27:43. The video shows the accident airplane descend with the red beacon flashing. The airplane impacts the roof of the metal building. The airplane then descends below the building and is no longer visible. At the time of the video, it is dark outside and there appears to be moisture on the ground.

The second camera angle shows the front of the metal building and is angled out toward the street and a second building. The video shows the accident airplane descend, impact the ground, the retaining wall, and then bounce. The navigation lights remain visible during the entire video. At the time of the video it is dark outside, street lighting is visible, and it is raining.