

CEN24LA172

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Helicopter after Recovery (Courtesy of FAA)



Photograph 2 - Substantial Damage to the Tailboom (Courtesy of FAA)



Photograph 3 - Closeup of Substantial Damage to the Tailboom (Courtesy of FAA)