

CEN24LA191

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident airplane (Courtesy of owner)



Photograph 2 - Holes in underside of left wing (Courtesy of owner)