

National Transportation Safety Board

Office of Aviation Safety
Central Region



CEN24LA204

INVESTIGATION PHOTOGRAPHS



**Photo 1 - Accident Site Overview
(Courtesy of Waco Regional Airport Manager)**



**Photo 2 - Airplane ground track
(Courtesy of Waco Regional Airport Manager)**



**Photo 3 - Airplane at accident site, right
(Courtesy of Waco Regional Airport Manager)**



**Photo 4 - Airplane at accident site, front
(Courtesy of Waco Regional Airport Manager)**



**Photo 5 - Airplane at accident site, left
(Courtesy of Waco Regional Airport Manager)**



**Photo 6 - Damage to engine mount tubes
(Courtesy of FAA)**