

[CEN24LA205]

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Helicopter Substantial Damage (Courtesy of Law Enforcement)



Photograph 2 - Airframe Substantial Damage (Courtesy of Law Enforcement)



Photograph 3 - Main Rotor System Substantial Damage (Courtesy of Law Enforcement)