

National Transportation Safety Board

Office of Aviation Safety
Central Region



CEN24LA210

INVESTIGATION PHOTOGRAPHS



**Photo 1 - Airplane at accident site, left
(Courtesy of Airplane Operator; Edited by NTSB)**



**Photo 2 - Airplane at accident site, front
(Courtesy of Airplane Operator)**



**Photo 3 - Airplane at accident site, front
(Courtesy of Airplane Operator)**



**Photo 4 - Forward fuselage, right
(Courtesy of Airplane Operator)**



**Photo 5 - Lower fuselage
(Courtesy of Airplane Operator; Edited by NTSB)**