

CEN24LA222

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of damage to fuselage (Courtesy of FAA)