

CEN24LA231

## INVESTIGATION PHOTOGRAPHS



Photograph 1 – Airplane right side (Courtesy of the pilot)



Photograph 2 – Airplane front (Courtesy of the pilot)



Photograph 3 –Damage (Courtesy of the pilot)



Photograph 4 –Fuselage damage (Courtesy of the pilot)