

CEN24LA239

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Overall view of the accident site (courtesy of the Morton County Sheriff's Office)



Photograph 2 - View of the front of the airplane at the accident site (courtesy of the Morton County Sheriff's Office)



Photograph 3 - View of the right side of the airplane at the accident site (courtesy of the Morton County Sheriff's Office)



Photograph 4 - View of the left side of the airplane at the accident site (courtesy of the Morton County Sheriff's Office)



Photograph 5 - View of the airplane recovered to the operator's hangar



Photograph 6 - View of the substantial damage sustained to the rudder



Photograph 7 - View of the engine being removed from the airframe



Photograph 8 - View of the engine removed from the airframe