

[CEN24LA246]

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Airplane (Courtesy of FAA)



Photograph 2 - Left Wing Substantial Damage (Courtesy of FAA)



Photograph 3 - Fuselage & Right Wing Substantial Damage (Courtesy of FAA)