

CEN24LA247

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of airplane as it came to rest (Courtesy of FAA)



Photograph 2 - View of bottom of fuselage showing exposed core material (Courtesy of FAA)