

CEN24LA263

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Left wing damage (Courtesy of accident pilot)