

CEN24LA265

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Airplane (Courtesy of FAA)



Photograph 2 - View of Airplane Cabin. Note flap handle position (Courtesy of FAA)