

[CEN24LA273]

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Airplane (Courtesy of FAA)



Photograph 2 - Right Wing Substantial Damage (Courtesy of FAA)