

CEN24LA291

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Airplane at accident site (Operator photo)**



**Photograph 2 - Airplane at accident site (Operator photo)**



**Photograph 3 - Firewall fuel filter bowl (Operator photo)**