

CEN24LA292

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane after Recovery (Courtesy of FAA)



Photograph 2 - Substantial Damage to Firewall (Courtesy of FAA)