

National Transportation Safety Board

Office of Aviation Safety
Central Region



CEN24LA297

INVESTIGATION PHOTOGRAPHS



Photo 1 - Airplane at accident site, right (Courtesy of FAA)



Photo 2 - Airplane at accident site, left (Courtesy of FAA)



Photo 3 - Left wingtip and aileron (Courtesy of FAA)