

CEN24LA321


INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the front of the airplane at the accident site (courtesy of the pilot)



Photograph 2 - View of the left side of the airplane at the accident site (courtesy of the pilot)



Photograph 3 - View of the rear of the airplane at the accident site (courtesy of the pilot)



Photograph 4 - View of the right side of the airplane at the accident site (courtesy of the pilot)