

CEN24LA342

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the engine mount installed in the airplane (courtesy of the Federal Aviation Administration)



Photograph 2 - View of the engine mount installed in the airplane (courtesy of the Federal Aviation Administration)



Photograph 3 - View of a portion of the engine mount removed from the airplane (courtesy of the Federal Aviation Administration)