

The Standard
ENGINE LOG

ASA-SF-2

☐ HUB

wo: GA1241

Propeller - page 1 of 1

Great Planes Aviation - [REDACTED] - Rochester, MN 55902 - [REDACTED]

N4081S **Hartzell, HC-C3YR-1, S/N: DY2503A** **October 12, 2021**
Hobbs: 2292.4 TACH: 3361.46

Next Inspection Due:

1. Complied with Annual Inspection in accordance with 14 CFR 43, Appendix D using Piper and Hartzell maintenance manuals as a guide.
2. AD's checked through this date.

Year: I certify this propeller has been inspected in accordance with an annual inspection and was determined to be airworthy. With respect to the work performed, this propeller is approved for return to service. Details of work performed are on file with Great Planes Aviation under work order: GA1241.

Date:

Next Inspection Due: Ryan Fay A&P/IA [REDACTED]

		Mech. Cert. # or Repair Station #
Year:	Total Time in Service	Description
Date:		
Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station #

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS ☐

wo: GA1492

Propeller - page 1 of 1

Great Planes Aviation - [REDACTED] - Rochester, MN 55902 - [REDACTED]

N4081S **Hartzell, HC-C3YR-1, S/N: DY2503A** **October 17, 2022**
HOBBS: 2292.4 TACH: 3500.37

Next Inspection Due:

1. Complied with Annual inspection in accordance with 14 CFR 43, Appendix D using Piper and Hartzell maintenance manuals as a guide.
2. AD's checked through this date.

Year: I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be airworthy. With respect to the work performed, this propeller is approved for return to service. Details of work performed are on file with Great Planes Aviation under work order: GA1492.

Date:

Next Inspection Due: Ryan Fay A&P/IA [REDACTED]

Date:	Time Since Overhaul	Mech. Cert. # or Repair Station #
Next Inspection Due:		

ENGINEERING

ASA-SE-2

wo: GA1756
Propeller · page 1 of 1


GREAT PLANES
AVIATION

Great Planes Aviation · [REDACTED]
Rochester, MN 55902 · [REDACTED]


Year: _____
N4081S
Hartzell, HC-C3YR-1, S/N: DY2503A
November 08, 2023

Date: _____
HOBBS: 2292.4
TACH: 3578.29

Next Inspection Due: _____

- Complied with annual inspection in accordance with 14 CFR 43, Appendix D using Piper and Hartzell maintenance manuals as a guide.
- AD's checked through this date.

I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be airworthy. With respect to the work performed, this propeller is approved for return to service. Details of work performed are on file with Great Planes Aviation under work order: GA1756.


 Ryan Fay A&P/IA [REDACTED]

Year: _____
Mech. Cert. # or Repair Station # _____

Date: _____

Next Inspection Due: _____

	Total Time in Service	Description
Year: _____		
Date: _____		
Next Inspection Due: _____	Time Since Overhaul	
		Mech. Cert. # or Repair Station # _____

AIRWORTHINESS DIRECTIVES ☐		
Year: _____ Date: _____ A.D. # _____ Next Inspection Due: _____	Total Hours _____	Complied by the following: _____ _____ _____ _____ _____ Mech. Cert. # or Repair Station # _____
Year: _____ Date: _____ A.D. # _____ Next Inspection Due: _____	Total Hours _____	Complied by the following: _____ _____ _____ _____ _____ Mech. Cert. # or Repair Station # _____