

CEN24LA344

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident site, power lines (Courtesy of private citizen)



Photograph 2 - Accident site, initial impact (Courtesy of airplane owner)



Photograph 3 - Accident site, airplane left side (Courtesy of private citizen)



Photograph 4 - Accident site, airplane right side (Courtesy of airplane owner)



Photograph 5 - Accident site, airplane bottom side (Courtesy of private citizen)