

National Transportation Safety Board

Office of Aviation Safety
Central Region



CEN24LA356

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane at Accident Site, Overview (Courtesy of Pilot)



Photograph 2 - Airplane at Accident Site, Fuselage (Courtesy of FAA)



Photograph 3 - Airplane Wreckage After Recovery (Courtesy of FAA)



Photograph 4 - Engine Overview (Courtesy of FAA)