

CEN24LA365

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Photo of the accident airplane (FAA Photo)



Photograph 2 - Damage to right side of fuselage (FAA Photo)



Photograph 3 - Damaged runway sign (FAA Photo)



Photograph 4 - Damage to right side of fuselage (FAA Photo)