

CEN24LA367

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Impact marks on runway (Courtesy of Cirrus Aircraft)



Photograph 2 - Impact marks on runway (Courtesy of Cirrus Aircraft)



Photograph 3 - Impact marks on ground (Courtesy of Cirrus Aircraft)



Photograph 4 - Separated engine (Courtesy of Cirrus Aircraft)



Photograph 5 - Back side of airplane (Courtesy of Cirrus Aircraft)



Photograph 6 - Front left side of airplane (Courtesy of Cirrus Aircraft)