

National Transportation Safety Board

Office of Aviation Safety
Central Region



CEN24LA374

INVESTIGATION PHOTOGRAPHS



Photo 1 - Airplane at accident site, rear (Courtesy of Grand County Airport Supervisor)



Photo 2 - Airplane at accident site, left (Courtesy of Grand County Airport Supervisor)



Photo 3 - Airplane at accident site, front (Courtesy of Grand County Airport Supervisor)



Photo 4 - Airplane at accident site, right (Courtesy of Grand County Airport Supervisor)



Photo 5 - Aft fuselage and tailwheel assembly (Courtesy of Grand County Airport Supervisor)